

Synkote Paints 14:40 4/3/89

D. Belyung

Set A

268791



View of center of south lab bench. Note the Poison Liquid NOS container.

This container was labeled epichlorohydrine which is a skin contact poison. This chemical is also incompatible with aluminum. A can of aluminum paste was found near this container to the left.



Synkote Paints 14:40 4/3/89

D. Belyang Set A

Photo of south end of lab bench
showing various laboratory containers.



SynKote Prints 4/3/89 14:45

D. Belyung Set A

View of North lab bench with
unlabeled containers.



SynKote Paints 1445 4/3/89

D. Belyung Set A

Photo of north lab bench showing
two open containers.



Synkote Prints 1445 4/3/89

D. Belyung Set A

TATS taking inventory of south lab
bench in level "B"



SynKote Paints 1450 4/3/89

D. Belyung

Set A

View of reactor room showing VATs
And miscellaneous drums with solids
inside.



Synkote Prints 1450 4/3/89

D. Belyung Set A

View of north side of reactor
room with 14 drums labeled paint
sludge.



Synkote Paints 1450 4/3/89

D. Belyung

Set A

View of 12 drums in reactor room, drums were labeled "waste paint sludge".



EXIT

NO SMOKING

4

4404

Level 400H

3

SynKote Paints 14:55 4/3/89

D. Belyung Set A.

Full view of north lab bench
note carboy below bench at center.



Synkote PAints 14SS 4/3/89

D. Belyung

Set A

TAT ~~is~~ taking inventory of north
lab bench.



Synkote Paints 14:55 4/3/89

D. Belyung

Set A

Full view of south lab bench
note crated poison at center.



Sy
NY 20 04

SynKole Prints 1505 4/3/09

D. Belyung Set A

View of drums At rear of site,
At east side of site.



SynKote Prints 15:05 4/3/89

D. Belyung

Set A

View look west of rear area
of site, note discolored soil.



Synkote Paints 15:10 4/3/89
D. Belyung Set A

TAT using explosimeter & radiation meter
to screen drums. Note triangular
warning label indicating that drums

are an explosion hazard when
empty.



Synkote Paints 15:10 4/3/89

D. Belyung Set A

TAT taking notes on location of
drums. Note ~~drums~~ some drums
were labeled with hazardous waste

labels, but no information was
found on these labels.



Synkote Paints 15:10 4/3/89

D. Belyung

Set A

TAT taking count of the
number of drum on the North
side of the site.



Synkote Paints 15:15 4/3/89

D. Belyung

Set A

View of yellow rusted salvage drum
~~and~~ in front, and black drum, in
back which gave elevated OVA readings.



Synkote Paints 15:17 4/3/89

D. Belyung

Set A

View of drum which was not sealed.
Elevated OVA readings were obtained
from the opening in this drum.



Synkote Prints 15:20 4/1/89
D. Belyung Set A

Two more drums with opened sides,
elevated reading on the OVA were
found in these openings.



Synkote Paints 15:20 4/3/89
D. Belyung Set A

View of drum with corroded
top. Elevated OVA readings were
obtained inside the hole on the left.



Synkote Paints 15:20 4/3/89

D. Belyung Set A

Photo of warning label on one of
the drums indicating a explosion
threat when empty.



Synkote Prints 15:25 4/3/89

D. Belyung Set A

View of a building drum onsite
in north west corner.



Synkote Paints 15:25 4/3/19

D. Belyung Set A

View of rusting overpack drums
located next to a parking lot at
a neighboring workplace.



SynKobe Prints 15:25 4/3/89

D Belyung Set A

View of drums looking south west.

Note business and residential homes
located nearby.



WcomL

HW

WcomL

3

SAVAGE DRUM

SAVAGE DRUM

SAVAGE DRUM

Synkote Prints 15:25 4/3/89

D. Belyung

Set A

View of west drum area looking
south, note residential homes
nearby.



Synkote Prints 15:30 4/3/89

D. Belyung Set A

View of drums with residential
homes in the background.



Synkote Prints 15:30 4/3/89

D. Belyung

Set A

View of rear of site looking east, site is enclosed with a fence. Note soil contamination

from leaking drum in center of photo.



Synkote Prints 15:30 4/3/89

D. Belyung Set A

View of drum area looking north
west at west end of site.

